

STUDIU DE MINIM DE COST LA GRINZI DE BETON ARMAT. Planşa I.





FIG.6 INTOCMIREA DALEI ŞI GRINZII SECUNDARE (E_x I si II)



Inginer: Ion M. Tomescu

Dec. 9/1928. an.